



field painting procedure

The entire surface of the pole should be scuff-sanded with a 320-grit, non-silicone sandpaper.

Second, the entire surface is to be washed with an industrial solvent and wiped clean with a lint-free painter's rag or tack cloth.

The finish coat should be an exterior quality air-dried acrylic enamel, or other paint that is compatible with TGIC polyester powder, to match fixture.